



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. W 078357

Loc. Marshall #1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>Surface</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall #1 April 30, 1961

Well No. 6 is located 990 ft. from N line and 990 ft. from W line of sec. 14

NE/4 Section 14 (1/4 Sec. and Sec. No.) 27N (Twp.) 9W (Range) 12W (Meridian)
Blanco - Rosoverde (Field) San Juan (County or Subdivision) N.M. (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Started: 11:30 p.m., April 30, 1961
Drilled 12 1/2" hole to 206'.
Ran 8-5/8" OD casing (24.5, J-55, RTG) set at 201' and cemented with 150 sacks regular cement. Cement circulated to surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Nicolls Oil Company

Address Drawer 510

Marathon

New Mexico

By _____

Title District Geologist