

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 077875

Unit Pipkin

NOV 21 1951

OIL CON. COM.

SUNDRY NOTICES AND REPORTS ON WELLS

		DIST. <u>3</u>
NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 19, 1951

Well No. 3 is located 990 ft. from N line and 990 ft. from E line of sec. 17

NE NE Sec. 17
(1/4 Sec. and Sec. No.)

27N
(Twp.)

10W
(Range)

N. M. P. M.
(Meridian)

Fulcher-Kutz
(Field)

SAN JUAN
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6080 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

TD 1960'.

On 11-12-51, ran 76 joints of 5-9/16" 14.65# LW Line Pipe with ST&C (1793').

Set @1793' w/100 sacks regular cement.

Held 500# for 8 hours. Top of cement by temp. survey 1235'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company EL PASO NATURAL GAS COMPANY

Address P.O. Box 997

Farmington

New Mexico

By ORIGINAL SIGNED E. J. COEL

E. J. Coel
Title Petroleum Engineer