



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office **Santa Fe**
Lease No. **0780009-C**
Unit **Ojo Amarillo**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Notice of Drill Stem Test	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 28, 1962

Well No. **1** is located **660** ft. from **XX** line and **660** ft. from **E** line of sec. **7**
SE/4, SE/4 **27-N** **13-W** **NMPN**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)



The elevation of the **G.L.** ~~surface~~ above sea level is **5995** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

D.S.T. No. 2 - Straddle Test, 5268-5412', Tool open 2.5 hrs., opened with fair to light blow to very light at end of test. ISIP 30 Min. 2350#, FSIP 1680#. Flow Press 605-905#. Hydrstatic Press in 2740#, Hyd. cut 2620#. Recovered 1800' drilling mud. Chart indicated bottom packer was holding.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Tidewater Oil Company**
 Address **Box - 1231**
Midland, Texas

By **R. H. Coe**
 Title **Dist. Prod. Manager**