

APPROVED

Form 70-11
(April 1955) Sgd.) J. W. LONG

JUN 19 1956

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-B350.4.
Approval expires 12-31-60.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Borough _____

Allottee Bullish FlatsLease No. 2444-1-1-1-1-1-1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Bullish FlatsMay 14,1956Well No. 2 is located 300 ft. from S line and 200 ft. from E line of sec. 20300 (4 Sec. and Sec. No.) 300 (Twp.) 300 (Range) 300 (Meridian)South 20 (Field) 300 (County or Subdivision) 300 (State or Territory)The elevation of the derrick floor above sea level is 4000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Spudsite 2444-1-1-1-1-1-1, May 14, 1956.

Run 5 1/2" 2444-1-1-1-1-1-1 and cemented with 150 lbs. cement, 150 lbs. cement, 150 lbs. cement.

Casing cemented. Tested casing with 500 psi pressure for 30 minutes. Pressure held.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AMERICAN OIL COMPANYAddress Box 400Farmington, New MexicoBy J. L.Title Manager

