

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYAllotted Navajo Allotted
Allottee Rollie Platano
Lease No. 2-149-220164

APPROVED			
	Orig. Sec.	LONG	
	ACTING	ENGINEER	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>2-149-220164</u>	<u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Rollie PlatanoMay 21, 1956Well No. 3 is located 3400 ft. from S line and 1600 ft. from W line of sec. 21SW/4 Section 21(1/4 Sec. and Sec. No.)
South ElmoreSW

(Twp.)

9W

(Range)

N. N. P. M.

(Meridian)

(Field)

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 4000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded: 12:00 p.m. May 21, 1956. Ran 6 jts. 8-5/8" casing set at 144' and cemented w/150 sacks regular cement w/25 cal-cium chloride. Cement circulated. Tested with 500# pressure for 30 minutes. Pressure held.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company SKELLY OIL COMPANY
Address Box 424, Farmington, New MexicoBy P. E. CooperTitle District Engineer

