UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry No	tices and Reports on W	ells
1. Type of Wel	1	RECEIVED	5. Lease Number SF-078936 6. If Indian, All. or Tribe Name 7. Unit Agreement Name
PO Box 428	il Inc. hone No. of Opera 9, Farmington, NN Well, Footage, S	OIL CON. DIV DIST. 3 ator 4 87499 (505) 326-9700	8. Well Name & Number Harmon A #3 9. API Well No. 10. Field and Pool W.Kutz Pic.Cliffs
Type of Sub		Type of A Abandonment Recompletion Plugging Back Casing Repair Altering Casing	11. County and State San Juan County, NM CE, REPORT, OTHER DATA Action Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection e Complete & Repair Well
It is in	cleaning out ope wellbore in the production. Appr prior to commenc operations will 7" production cs to BLM requireme 1513'. Reset BP, 2 3/8" production etailed plan of o	the Pictured Cliffs in hole 1430-1513'. Particularly coal and composed will be received ing work. be: Pull 1" productions. If necessary, csg wents. Retrieve BP, CO	mingled w/existing from NMOCD for commingling on the third section to the comming the section to the control of
Signed Jean (This space for APPROVED BY	or Federal or Sta	Title	Affairs Date3-30-92 APPROVED Date 1992
		COONE	AREA MANAGER