


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **SANTA FE**
070572-A
Lease No. **3 1/4 of Sec. 9 in**
Designated Strip Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Block #5
C SW NE SW

July 17, 1951

Well No. **5** is located **1650** ft. from **N** line and **1650** ft. from **E** line of sec. **9**
3 1/4 **9** **27N** **11W** **N.M.P.M.**
W. Santa Canyon (Twp.) **Santa Juan** (Range) **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6207** ft. and **6198'** Ord.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

- Spudded 7/9/51.
- Ran 5 joints (99') of 8-5/8" casing at 108' KB with 90 sacks of regular cement and circulated to surface. Plug down at 3:30 P.M.
- Tested casing with 500# pressure held for 30 minutes and showed no drop in pressure.
- After drilling plug, tested for 30 minutes with 300#. The water level remained stationary.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

THE PROCTER ASBESTOS COMPANY


Company **420 BOSTON BUILDING**

Address **DENVER, COLORADO**

By **Denman S. Galbraith**
Denman S. Galbraith, Geologist
Title

Land Office _____
 Lease No. _____
 Unit _____

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF A TEST SHOOT-OUT
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SEEDING OR AMENDING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF A TESTING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF A DRAINING OR REPAIR
NOTICE OF INTENTION TO SHUT OR ABANDON	SUBSEQUENT REPORT OF A STOPPAGE
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HIS ORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK, SIGNATURE OF REPORT, NOTICE, AND DATA)

_____ 19____

_____ is located _____ ft. from _____ line and _____ line of sec. _____

_____ (County or Subdivision) _____ (Town or Township) _____ (Range and Section)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands, show times, weights, and lengths of pipes, etc.; indicate mudlogging jobs, cementing, etc.)

I understand that this plan of work must receive approval in writing by the Geological Survey before any work is commenced.

Company _____

Address _____

By _____
