


(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe**
Lease No. **SP-073872**
Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 22, 19 **57**

Carter-Howles

Well No. **71** is located **196** ft. from **N** line and **1336** ft. from **E** line of sec. **4**

SE 1/4 sec. 4 **27 N., 11 E.** **T.M.P.M.**

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

West Rutz **San Juan** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5194** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforations 1972-1982, 1983-1994 have been squeezed with 15 sx.
5 1/2" csg. was cut off at 1336.
Cement plugs were set from 1336-1436 and 930-990
A 10sx. plug was set at surface
A marker with well data was set in surface csg.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Ted E. White**
Address **115 Seventh St., NE**
Albuquerque, New Mexico

By **L.E. Kellyford**
Title **Agent**