

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-24224

5. LEASE INFORMATION AND NUMBER

I-89-IND-57

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribe

7. UNIT NAME

Table Mesa

8. FARM OR TRACT NAME

24

9. WELL NO.

Table Mesa, Penn

10. FIELD AND POOL, OR WELLCASE

Sec 4 T27N R17W

11. COUNTY

San Juan New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

John F. Staver

3. ADDRESS OF OPERATOR

Box 51 Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1750 FSL

1750 FWL

14. PERMIT NO.

15. MEASUREMENTS (Show whether SP, MP, GP, etc.)

5369

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALONG CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE STIMULATION

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

REPAIRING CASING

REPAIRING EQUIPMENT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths to all markers and depth points pertinent to this work.)*

Plugging operation was completed

September 1974

Pits filled & dry hole marker elected

December 1974

#1 Plug 7469-6850	41sk.	spotted down tubing in 4 1/2" casing
#2 Plug 6100-6200	17sk.	spotted down tubing in 7" casing
#3 Plug 5096-5126	25sk.	spotted down tubing in 9 5/8" casing
#4 Plug 4275-4375	33sk.	spotted down tubing in 9 5/8" casing
#5 Plug 2900-2800	33sk.	spotted down tubing in 9 5/8" casing
#6 Plug 75-0	50sk.	spotted down tubing in 13 3/8" casing

10.4 lb. mud was spotted between cement plugs

Location is ready for inspection

RECEIVED

MAR 1975

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Manager

DATE February 24, 75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: