



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Ant. Fe
Lease No. 07024
Unit 011

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
NOV 13 1961
U.S. GEOLOGICAL SURVEY
FAC. SECTION, ANT. FE, MEXICO

Well No. 1-1 is located 1650 ft. from N line and 1650 ft. from E line of sec. 6.
NE/4 Sec. 6 27N 10W S.M.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Fulcher-ruta San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5020 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is intended to plug and abandon this well in the following manner:

1. Spot 25 sacks of cement across pay interval.
2. Find free point and cut off casing.
3. Spot cement plug on casing stub and pull casing.
4. Spot 150' cement plug at surface.
5. Install permanent 4' x 4' marker.

This well is to be plugged and abandoned because it was never commercial.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 904
Farmington, New Mexico

By CRISTINA GARCIA
Title Petroleum Engineer