


COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078936
Unit NW/4 Sec. 2



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 1, 1951

Well No. 2 Harmon is located 1650 ft. from N line and 1650 ft. from W line of sec. 2

NW/4 Sec. 2

(1/4 Sec. and Sec. No.)

27N

(Twp.)

12W

(Range)

NMPM

(Meridian)

West Kutz Canyon

(Field)

San Juan County

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 5933 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

The well was shot 8-30-51 with 200 quarts of solidified nitro glycerin from 1610-1693.

The shot went off on time and the calseal plug was drilled and the well cleaned out to the total depth of 1693. When the well was shut in the gas flow was estimated at 4 million cubic feet.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Danube Oil Company

Address 213 First National Bank Building

Amarillo

Texas

By [Signature]

Title Agent