## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No	27055-A
Unit	Granting

SUNDRY NOTICES A	ND REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL  NOTICE OF INTENTION TO CHANGE PLANS  NOTICE OF INTENTION TO TEST WATER SHUT-OFF  NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.  NOTICE OF INTENTION TO SHOOT OR ACIDIZE.  NOTICE OF INTENTION TO PULL OR ALTER CASING  NOTICE OF INTENTION TO ABANDON WELL.	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY
(INDICATE ABOVE BY CHECK MARK )	NATURE OF REPORT, NOTICE, OR OTHER DATA)
	Horeb 12 , 19_51
Well No. 3-4 is located 100 ft. from	(Range) (Meridian)
Large Xxt.	du
(County or	Subdivision) (State or Territory)
The elevation of the derrick floor above sea leve	el is 524 ft.
(State names of and expected depths to objective sands; show sizes, ing points, and all oth	, weights, and lengths of proposed casings; indicate mudding jobs, cemen er important proposed work)
	(min; 200' set at 300' with 120 sacks
Seld XX lbs. pressure for 30 min	ntes. This w.
I understand that this plan of work must receive approval in wri	ting by the Geological Survey before operations may be commenced.
Company SAN MAY PROPERTION COMPANY	
Address 12 April Court Avenue	5. 7.
Farmington, New Mexico	By
	Title Petrolem Ingineer

U. S. GOVERNME:NT PRINTING OFFICE 18-0497-0