

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 077875

Unit SE/4 Sec. 17

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ April 7, 1953 _____, 19_____
 Turner-Pickin
 Well No. 3 is located 1650 ft. from ~~(N)~~
 {S} line and 990 ft. from ~~(E)~~
 {S} line of sec. 17
 SE 1/4 Sec. 17 27N 10W N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
 Fulcher-Kutz San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5975 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud: April 5, 1953.

Set 8-5/8 32# casing at 100 ft. with 85 bags of Ideal regular cement and 100 lb. of Calcium Chloride.

After waiting for cement to set, tested for water shgt with 500 snig.
Pressure held for 30 minutes. No indicated drop.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. Glenn Turner
c/o San Juan Drilling Co.
Address Box 728 -Farmington, New Mexico.

Home Office: 1711 Mercantile Bank Bldg.

Dallas 1, Texas.

Original signed by
By Charles S. Peters

Title Geologist