## State of New Mexico Energy, Minerals and Natural Resources Department OIL CONSERVATION DIVISION

Sundry Notices and Reports on	Wells
1. Type of Well GAS	API NO. (assigned by OCD)  5. Type of Lease State 6. State Oil & Gas Lease #
<ol> <li>Name of Operator         Meridian Oil Inc.</li> <li>Address of Operator         PO Box 4289, Farmington, NM 87499</li> <li>Well Location         840'FNL, 1750'FWL         Sec.32,T-27-N,R-10-W NMPM San Juan County</li> </ol>	E-2659-5  7.Lease Name/Unit Name Huerfano Unit 8.Well No. 228  9.Pool Name or Wildcat Basin Dakota
X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back X Casing Repair	Non-Routine Fracturing
12.Describe proposed or completed operations:  It is intended to perform a casing repair per the diagram.	
CIT (	T1 6 1991 CON. DIV. DIST. 3
SIGNATURE Sugar Shad fued Regulator (KAS)	y Affairs <u>10-14-91</u> Date
(This space for State use)  APPROVED BY Original Signed by CHARLES GHOLSON TITLE	DATE

CONDITION OF APPROVAL, IF ANY:

## HUERFANO UNIT #228 DK Repair Procedure C 32 27 10

- Comply to all NMOCD, BLM, & MOI, rules & regulations.
   MOL and RU completion rig. NU 6" 900 series BOP with flow tee and stripping head. Test operation of rams. NU bloose line and 2-7/8" relief line.
- Drop standing valve to seat in S.N. @ 6444'. Test tbg to 2500 psi. TOH W/6475' (211 jts) 2-3/8" Dakota tbg. Remove standing valve.
- TIH w/ret BP fullbore pkr combo & locate csg leak in 4-1/2".
   Anticipate csg leak above 850'.
- 4. When csg leak is located, set ret BP about 100' below leak & dump 10 sx sand on top of ret BP. With pkr about 300' above leak, squeeze leak w/cmt as required. Attempt to circ cmt out bradenhead valve.
- 5. TIH w/3-7/8" bit on 2-3/8" tbg & drill & clean out w/air/mist to below csg leak. Pressure test to 800 psi. If necessary, resqueeze as necessary.
- 6. When sq holds 800 psi, C.O. to RBP. TOH. TIH w/retrieving tool & retreive RBP. TOH.
- 7. TIH w/open ended 2-3/8" tbg & C.O. to 6500' w/air/mist. TOH.
- 8. TIH w/tbg open ended w/S.N. one jt above bottom on 2-3/8" tbg & land @ 6470'.
- 9. Resume production from Dakota.

Approve:					
	R.	F.	Headrick		

## HUERFANO UNIT #228 DK

UNIT C SECTION 32 T27N R10W SAN JUAN COUNTY, NEW MEXICO

