UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEA	SE	1111		
	_SF	077123	12	w to	2: *
ŝ.	IF IN	IDIAN, ALLO	TTEE O	R TRIBE	NAME

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	Warren
Well Galler	9. WELL NO.
2. NAME OF OPERATOR	#11
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Aztec Picture Cliffs
P.O. Box 4289, Farmington, NM 87499-4289	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 13, T-28-N, R-9-W
AT SURFACE: 810'N, 810'E, Sec. 13, T28N, R9W AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15 45
A. Street	15 EEEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL SUBSEQUENT REPORT SUBSEQUENT REPOR	~0
RACTURE TREAT	1984 1
HOOT OR ACIDIZE	
DEPAIR WELL	(NOTE: Report results of multiple completion or zone
NULTIPLE COMPLETE	(NOTE::Report results of multiple completion or zone GICAL N. (Plange on Form 9–330.)
HANGE ZONES	
BANDON*	
other) Progress Report	
Well is making around 90 MCF/D. The chart water is being removed. Line pressure is aro	t indicates more and more ound 170 lbs.
Subsurface Safety Valve: Manu. and Type	Set @Ft.
8. I hereby certify that the foregoing is true and correct	
Production	
IGNED COLOR TITLE Engineer	DATEDecember 13, 1982
(This space for Federal or State offic	e use)
PPROVED BY TITLE TITLE	DATE
CCEPTED FOR RECORD	

DEC 1 4 1982	de
FARMINGTO NO.	