
UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wel	ls	
1. Type of Well GAS	5. Lease Number SF-077384 6. If Indian, All. or Tribe Name	
	7. Unit Agreement Name	
2. Name of Operator Meridian Oil Inc.	Huerfano Unit 8. Well Name & Number Huerfano U Com #118	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.	
4. Location of Well, Footage, Sec., T, R, M 1650'FSL, 1650'FEL Sec.30, T-27-N, R-10-W, NMPM	10. Field and Pool Basin Dakota 11. County and State San Juan Co, NM	
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE Type of Submission Type of Act		
x Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back	<pre>Change of Plans New Construction Non-Routine Fracturing</pre>	
Final Abandonment Casing Repair Altering Casing	<pre>Water Shut off Conversion to Injection n</pre>	
13. Describe Proposed or Completed Operations		
It is intended to clean out and stimulate the sub She attached procedure and wellbore diag She attached procedure and wellbore diag She attached procedure and wellbore diag		
(X) (T)	01 1902	
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		
14. I hereby certify that the foregoing is true and c	orrect.	
Signed Malhueld (KAS) Title Regulatory Af	<u>fairs</u> Date _4-29-92	
(This space for Federal or State Office use) APPROVED BY Title	APPROVED Bake) 0 1997	
CONDITION OF APPROVAL, if any:	CAREA MANAGER	

HUERFANO UNIT COM #118 DK

UNIT J SECTION 30 T27N R10W SAN JUAN COUNTY, NEW MEXICO

AFTER WORKOVER



Recommended Procedure

HUERFANO UNIT COM #118 DAKOTA UNIT J SECTION 30 T27N R10W San Juan County, N.M. Expense Workover

- 1. Test location anchors & dig blow pit.
- 2. MOL and RU completion rig. NU 6" 900 series BOP and stripping head. Test operation of rams. NU 2-7/8" relief line with 3000 psi gate valves on tubing head. Blow well down.
- 3. If necessary, kill well w/1% KCL water. Drop standing valve to seat on S.N. @ 6247' & test tub to 2000 psi. TOH w/2-3/8" tbg and Baker Lokset pkr. Remove standing valve. TIH w/3-7/8" bit on tested 2-3/8" tbg. and cleanout to PBTD (6326') w/air/mist. TOH.
- 4. Rerun 2-3/8" tbg. & land @ 6120' w/redressed Lok-set pkr @ 4330'. Run pump out plug in standard seating nipple one jt above open ended bottom. Pump out plug.
- 5. Stimulate Dakota perfs w/1000 gal. 15% HCL acid at low rate. Nitrify w/400 SCF/BBL Run 100 mcf-N2 pad and flush acid w/N2. Run the following additives:

2 gal. I17 corrosion inhibitor

5 gal. XR2L Fe sequestering

2 gal. LT21 silt suspender 1 gal. aquaflow non-emulsifier

- 6. Flow well until it dies or stablizes. Shut-in well. Release rig.
- 7. After 3 day buildup, return well to production.

Approve:

R. F. Headrick

VENDOR:

Acid & N2: Western 327-6222







Job separation sheet

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		
Sundry No	otices and Reports on We	lls
1. Type of Well GAS	DECENTED JUNI 1 1992	 Lease Number SF-077384 If Indian, All. or Tribe Name Unit Agreement Name
 Name of Operator Meridian Oil Inc. Address & Phone No. of Oper PO Box 4289, Farmington, No. Location of Well, Footage, 1650'FSL, 1650'FEL Sec.30, 	ON. CON. CON. CON. CON. CON. CON. CON. C	Huerfano Unit 8. Well Name & Number Huerfano U Com #118
12. CHECK APPROPRIATE BOX TO Type of Submission Notice of Intent _x_ Subsequent Report	Type of A	
Final Abandonment 13. Describe Proposed or Com	_x_ Other - stimulati pleted Operations	on
Stimulate Dakot. Flow back. Release 06-05-92 Pump corrosion 100#/15 min. H Townsend.	jts 2 3/8", 4.7#, J-55 7'. Pkr set @ 4340'. ND a perfs w/1000 gal. 15% ased rig. inhibitor down backside. eld 400#/30 min. Pressu	8rd EUE tbg landed @ BOP. NU master valve. HCl acid and N2. SI. PT backside 500#, lost re test approved by W. RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED
14. I hereby certify that the Signed leggy Madhuel		·
(This space for Federal or St APPROVED BY CONDITION OF APPROVAL, if any	Title	ACCEPTED FOR BECORD
		JUN 1 0 1992 FARMINGTON RESOURCE AREA Y