below.) AT SURFACE:

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

1770' FNL - 1100' FWL

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Bengal
	9. WELL NO. C-6
	10. FIELD OR WILDCAT NAME WAW Fruitland PC
	140 COUNTY OF PARISH 13 STATE

San Juan 14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* spud and surface csq (other)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

> Moved in and rigged up Morrow Drlg Co. Spudded 7-7/8" hole @ 11:45 a.m. Drlg to 32'. Ran 1 jt 5-1/2" OD 14# K-55 ST&C csg. TE 31.62' set @ 32' GR. Cemented to surface w/8 sx. Job complete 2:20 p.m. 8-7-79.

Subsurface Safety Valve: Manu. and Type foregoing is true and correct 18. I hereby certify hat the - 8-14-79 Agent DATE TITLE __ (This space for Federal or State office use) DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

mill