UNITED STATES DEPARTMENT OF THE INTERIOR

				Budget Bureau No. 42-R1424			
	5.	LEASE SF	078390				
	6.	IF INDIAN	i, ALLOTT	EE OR TR	IBE NAM	1E	
nt	7.	UNIT AG	REEMENT	NAME			
	8.	FARM OR Jones	LEASE NA	ME		; 5	
	9.	WELL NO 3A) .	,	₹.		
	10. FIELD OR WILDCAT NAME Blanco Mesa Verde						
7	11. SEC., T., R., M., OR BLK. AND SURVE AREA Sec. 15, T-28-N, R- N.M.P.M.						
	12.	COUNTY San Ju	OR PARIS		TATE Mexi	co	
 E.	14.	API NO.					

GEOLOGICAL SURVEY	G. IT INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas sa	8. FARM OR LEASE NAME Jones A		
well well well other	9. WELL NO.		
2. NAME OF OPERATOR	3A		
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Blanco Mesa Verde		
P.O. Box 289, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 15, T-28-N, R-8-W N.M.P.M.		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 840'N, 830'W			
AT SURFACE:	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL:	San Juan New Mexico		
AT TOTAL DEPTH:	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6378 GL		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF			
FRACTURE TREAT SHOOT OR ACIDIZE T			
REPAIR WELL	AIOTE: Barrier Harris Harris		
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)		
MULTIPLE COMPLETE			
CHANGE ZONES			
ABANDON*			
(other)			

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- 11-12-79: Spudded well. Drilled surface hole.
- Ran 7 joints 9 5/8", 36#, K-55 surface casing 291' set at 304'. 11-13-79: w/325 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.

Subsurface Safety Valve: Manu. and Type _ Set @ at the foregoing is true and correct Drilling Clerk DATE _ November 13, 1979 (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

See Instructions on Reverse Side