## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9-331 Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES  DEPARTMENT OF THE INTERIOR	5. LEASE SF 078390
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WI	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME Jones A
1. oil gas well X other  2. NAME OF OPERATOR	9. WELL NO. 2A
31 Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME S. Blanco PC, Blanco M.V.
Box 289, Farmington, New Mexico 87401  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 930'S, 1830'E AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	01 11. SEC., T., R., M., OR BLK. AND SURVEY OR Sec. 11, T-28-N, R-8-W N.M.P.M.
	12. COUNTY OR PARISH 13. STATE San Juan New Mexico
	NOTICE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6252 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPOR  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone
REPAIR WELL	(140 LE. Report results of multiple completion of zone

AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	_ 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15 SISVATIONS (SHOW DE KED AND WE)
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6252 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	
ABANDON*	
(other)	
<ul> <li>17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly strincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin</li> <li>12-29-79: TD 3193'. Ran 80 joints 7", 20#, Kat 3193'. Cemented w/297 cu. ft. cemented w/</li></ul>	ent to this work.)*  55 intermediate casing 3182' set
minutes. Top of cement 1800'.	
1-2-80: TD 5490'. Ran 76 joints 4 1/2", 10 3052-5490'. Float collar set at 54 cement. WOC 18 hours.	5#, K-55 casing liner 2438'. Set 71'. Cemented w/ 425 cu. ft.
	A JAM Groom
	A Part of the second
Subsurface Safety Valve: Manu. and Type	Set @
18. I hereby certify that the foregoing is true and correct	Dias. 3
	lank January 3 1980
0101120	
(This space for Federal or State	
APPROVED BY TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY: 2000 MUTE IN RUE

\*See Instructions on Reverse Side

**W** 33 80

FARMA D. CAC.