UNITED STATES DEPARTMENT OF THE INTERIOR

	Form Approved. Budget Bureau No. 42–R1424		
	5. LEASE SF-077874		
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
rent	7. UNIT AGREEMENT NAME		
	8. FARM OR LEASE NAME Hanks		
	9. WELL NO. 12-E		
	10. FIELD OR WILDCAT NAME Basin Dakota		
17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 7, T27N, R9W		
	12. COUNTY OR PARISH 13. STATE San Juan New Mexico		
 CE,	14. API NO.		
	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
(NOTE: Report results of multiple completen or some change on Form 9–330.) OIL CON. DIST. 3			
state is d tiner	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and it to this work.)*		
1 (6950', 6956', 6962', 6968', 11 holes). gel 1% KCl water and 74,800#		
	psi. , 4.70#, J-55, EUE tubing at 7061'.		

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WE (Do not use this form for proposals to drill or to deepen or plug back to a reservoir, Use Form 9–331–C for such proposals.)	i .
1. oil gas well other	Hanks 9. WELL NO.
2. NAME OF OPERATOR Southland Royalty Company	12-E 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Drawer 570, Farmington, N.M. 87401	Basin Dakota
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See sp	
AT SURFACE: 1020' FSL & 725' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF N	NOTICE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT TEST WATER SHUT OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Perforation & Stimulation X Production Tubing Report X	(NOTE: Report results of multiple completen or cone change on Form 9–330.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Cle including estimated date of starting any proposed work. If measured and true vertical depths for all markers and zones	well is directionally drilled, give subsurface locations and
7010', 7022', 7038', 7049', 70	s 30# gel 1% KCl water and 74,800#
3/29/81 Landed 226 joints (7050') of	2-3/8", 4.70#, J-55, EUE tubing at 7061'.
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED TITLE Drilli	
(This space for Federal of	or State office use)
APPROVED BY TITLE TITLE	DATE COULPTED FOR RECORD

APR 01 1981

FARMINGTON DISTRICT