

N


30-045-26096

9-19-84

F. Loc. 660/S; 1980/W Elev. 5536 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
SGrav. _____ 1st Del. Gas

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS		NIID X	Well Log	TEST DATA							Ref.No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfo								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											

NSX-R-7461

Acres 160

P
o

Bureau of Land Management, Navajo 28

No. 1

Caller Service 4104
Farmington, New Mexico 87409

FEB 26 1986

CERTIFICATE--RECEIVED REQUESTER

Petroleum Energy, Inc.
P.O. Box 1507
Durango, CO 81302-1507

Gentlemen:


Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. Co. 1-25 Navajo, SE/4SW/4 sec. 34, T. 27 N., R. 18 W., San Juan County, New Mexico, lease WCC-C-14-20-5420.
2. Co. 3-24 Navajo, SE/4SW/4 sec. 34, T. 27 N., R. 18 W., San Juan County, New Mexico, lease WCC-C-14-20-5420.

As discussed with Mr. John Keller, agent for your Company on February 17, 1986, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,


for Nat Millerbach
Area Manager

Enclosures

cc:
WCC

FEB 27 1986
CIVIL
BUREAU

ABANDONED LOCATION