## **DEVIATION REPORT**

Name of Company

Burlington Resources Oil & Gas Company

Lease Name and Number HUERFANITO UNIT #51R

**Pool and Formation**Ballard Pictured Cliffs

Address

P. O. Box 4289, Farmington, NM 87499 Sec. Twn. Rge.

-920 FSL -1,555 FWL

36 027N County 009W

SAN JUAN

Depth (Ft.)	<b>Deviation (Degrees)</b>
0	.00.
143	.25
342	2.75
497	.75
653	1.00
934	1.00
1,428	1.00
1,954	1.25
2,265	1.00

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for BURLINGTON RESOURCES OIL AND GAS CO., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 8th day of April, 1999

Notary Public in and for San Juan County, New Mexico Ny commission expires August 17, 2000

DEGESVED N JUN 2 8 1999

OIL GOM. DIV. DIST. 3