

Santa Fe

Land Office

Lease No.


07711

Unit

Storey

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 11, 19 57

Well No. **10-C (1M)** is located **1090** ft. from **N** line and **1650** ft. from **E** line of sec. **35**

SW Section 35
(¼ Sec. and Sec. No.)

29E
(Twp.)

9N
(Range)

N.M.P.M.
(Meridian)

So. Blanco Ext. & Blanco
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **6146** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 2-28-57, total depth 2495'.

Ran 84 joints 7-5/8", J-55, 26.4#, Casing (2484) set at 2494'
with 100 sacks regular cement, 100 sacks Pozmix, 50# Floccle and 4# Gel.
Held 1000# 30 minutes.

Top of cement by temperature survey at 1200'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may commence.

Company **El Paso Natural Gas Company**

Address **Box 997**

Farmington, New Mexico

By **ORLANDO E. R. OBERLY**

Title **Petroleum Engineer**

