



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 622085
Unit Umler

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 25, 1954

Well No. 3 Federal located 300 ft. from N line and 1750 ft. from E line of sec. 36SE Sec. 36 28N 10W NMPM
(Of Sec. and Sec. No.) (Twp.) (Range) (Meridian)Fulcher Kutz San Juan New Mexico
(Name) (County or Subdivision) (State or Territory)The elevation of the ^{ground}derrick floor above sea level is 5959 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

100' 10 3/4" 100' w/125 Sx

1900' 7" csg. with 100 sx

Pictured Cliffs formation T. D. 2000'



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company McMillan & WhiteAddress 4201 AlabamaEl Paso, TexasBy Jay J. HarrisTitle Consulting Geologist