


FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: <u>75223</u> Location: <u>Jennayah A-1</u> Operator #: <u>0203</u> Operator Name: <u>Amece</u> P/L District: <u>Blanco</u> Coordinates: Letter: <u>H</u> Section <u>36</u> Township: <u>28</u> Range: <u>9</u> Or Latitude _____ Longitude _____ Pit Type: Dehydrator ☒ Location Drip: ☒ ^{cmc 5/17/94} Line Drip: _____ Other: _____ Site Assessment Date: <u>5/17/94</u> Area: <u>03</u> Run: <u>82</u>
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside ☒ (1) Outside ☐ (2) Land Type: BLM ☐ (1) State ☐ (2) Fee ☐ (3) <i>Denizogical Navajo Tribe</i> DEPUTY OIL & GAS INSPECTOR SEP 11 0 1996 Depth to Groundwater Less Than 50 Feet (20 points) ☒ (1) 50 Ft to 99 Ft (10 points) ☐ (2) Greater Than 100 Ft (0 points) ☐ (3) Wellhead Protection Area : Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) ☒ (1) 200 Ft to 1000 Ft (10 points) ☐ (2) Greater Than 1000 Ft (0 points) ☐ (3) Name of Surface Water Body <u>Blanco Canyon</u> (Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream ☒ (1) < 100' (Navajo Pits Only) ☐ (2) > 100' TOTAL HAZARD RANKING SCORE: <u>40</u> POINTS
REMARKS	Remarks : <u>Redline - Inside, Vuln. - Inside</u> <u>3 pits. Dig & Haul 1. Pit Dry. Site next to Blanco Canyon</u> <u>Dig & Haul</u>

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 124° Footage from Wellhead 242'
b) Length : 13 Width : 12 Depth : 3

ORIGINAL PIT LOCATION



REMARKS :

Pictures @ 9:20 (9-13)
End Dump

REMARKS

Completed By:

Cory Chase
Signature

5/17/94
Date

FIE/ PIT REMEDIATION/CLOSURE FORM

GENERAL

Meter: 75233 Location: JENNAPAH A-1
 Coordinates: Letter: H Section 36 Township: 28 Range: 9
 Or Latitude _____ Longitude _____
 Date Started : 6-1-94 Area: 0.3 Run: 82

FIELD OBSERVATIONS

Sample Number(s): KPH 74
 Sample Depth: 12' Feet
 Final PID Reading 003 PID Reading Depth 12' Feet
 Yes No
 Groundwater Encountered ☐ (1) ☒ (2) Approximate Depth _____ Feet

CLOSURE

Remediation Method :
 Excavation ☒ (1) Approx. Cubic Yards -0-
 Onsite Bioremediation ☐ (2)
 Backfill Pit Without Excavation ☐ (3)
 Soil Disposition:
 Envirotech ☐ (1) ☒ (3) Tierra
 Other Facility ☐ (2) Name: _____
 Pit Closure Date: 6-1-94 Pit Closed By: B & F

REMARKS

Remarks : Soil looked clean dug sample hole to 12'
look heard head space PID 003. Closed Pit

Signature of Specialist: Kelly Padilla



40

FIELD SERVICES LABORATORY

ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

SAMPLE NUMBER:

Field ID

Lab ID

MTR CODE | SITE NAME:

SAMPLE DATE | TIME (Hrs):

SAMPLED BY:

DATE OF TPH EXT. | ANAL.:

DATE OF BTEX EXT. | ANAL.:

TYPE | DESCRIPTION:

N/A

REMARKS:

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE	10.25	MG/KG	1			
TOLUENE	10.25	MG/KG	1			
ETHYL BENZENE	0.035	MG/KG	1			
TOTAL XYLENES	0.37	MG/KG	1			
TOTAL BTEX	0.91	MG/KG				
TPH (418.1)	110	MG/KG			1.97	28
HEADSPACE PID	3 0.05 ^{7/14/94}	PPM				
PERCENT SOLIDS	86.0	%				

- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

The Surrogate Recovery was at 98 % for this sample All QA/QC was acceptable.

Narrative:

ATL results attached.

DF = Dilution Factor Used

Approved By:

Date:


7/14/94



Analytical **Technologies**, Inc.

2709-D Pan American Freeway, NE Albuquerque, NM 87107
Phone (505) 344-3777 FAX (505) 344-4413

ATI I.D. **406313**



June 10, 1994


El Paso Natural Gas
P.O. Box 4990
Farmington, NM 87499

Project Name/Number: PIT CLOSURE 24324

Attention: John Lambdin

On **06/03/94**, Analytical Technologies, Inc., (ADHS License No. AZ0015), received a request to analyze **non-aqueous** samples. The samples were analyzed with EPA methodology or equivalent methods. The results of these analyses and the quality control data, which follow each set of analyses, are enclosed.

If you have any questions or comments, please do not hesitate to contact us at (505) 344-3777.


H. Mitchell Rubenstein, Ph.D.
Laboratory Manager

MR:jd

Enclosure

GAS CHROMATOGRAPHY RESULTS

TEST : BTEX (EPA 8020)
 CLIENT : EL PASO NATURAL GAS ATI I.D.: 406313
 PROJECT # : 24324
 PROJECT NAME : PIT CLOSURE

SAMPLE ID. #	CLIENT I.D.	MATRIX	DATE SAMPLED	DATE EXTRACTED	DATE ANALYZED	DIL. FACTOR
13	945329	NON-AQ	06/01/94	06/06/94	06/07/94	25
14	945330	NON-AQ	06/01/94	06/06/94	06/07/94	1
15	945331	NON-AQ	06/01/94	06/06/94	06/07/94	1
PARAMETER			UNITS	13	14	15
BENZENE			MG/KG	1.1	<0.25	<0.025
TOLUENE			MG/KG	43	<0.25	<0.025
ETHYLBENZENE			MG/KG	10	0.035	<0.025
TOTAL XYLENES			MG/KG	110	0.37	0.054

SURROGATE:

BROMOFLUOROBENZENE (%) 35 98 94

*OUTSIDE ATI QUALITY CONTROL LIMITS DUE TO MATRIX INTERFERENCE