Form 9-331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

SF 077085

| GEOLOGICAL SURVEY | SF 077085 |
|---|--------------------------------------|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | 6. IF INDIAN, ALLOTTED OR TRIBE NAME |
| OIL GAS XX OTHER | 7. UNIT AGREEMENT NAME |
| NAME OF OPERATOR Tenneco Oil Company | 8. FARM OR LEASE NAME Omler "A" |
| ADDRESS OF OPERATOR | 9. WELL NO. |

NAMI 8. ADDR LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface P. O. Box 1714, Durango, Colorado 10. FIELD AND POOL, OR WILDCAT Basin Dakota 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 790' FWL 790' FSL Sec. 26, T28N, R10W 12. COUNTY OR PARISH 18. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 5868 GR San Juan N. Mex.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16.

| NOTICE OF I | NTENTION TO: | | SUBSEQUENT | REPORT OF: |
|---------------------|----------------------|---|--|----------------------------|
| L1 | ſ | | | |
| TEST WATER SHUT-OFF | PULL OR ALTER CASING | | WATER SHUT-OFF | REPAIRING WELL |
| FRACTURE TREAT | MULTIPLE COMPLETE | | FRACTURE TREATMENT | ALTERING CASING |
| SHOOT OR ACIDIZE | ABANDON* | | SHOOTING OR ACIDIZING X | ABANDONMENT* |
| REPAIR WELL | CHANGE PLANS | _ | (Other) | ultiple completion on Well |
| (Other) | Į | | (Note: Report results of m Completion or Recompletion | Report and Log form.) |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up completion rig 7-10-65. Cleaned out to 6511 PBTD. Spotted 250 gal. acid. Logged. Perf 4 holes/ft 6450-6411. Frac perfs w/30,000 lbs. sand and 43,450 gal. water. Set BP at 6400. Perf 4 holes per ft 6296-6267. Perf 2 holes/ft 6385-6349. Frac w/88,540 gal. water and 80,000 lbs. sand. Drilled out BP and cleaned out to 6511. Released rig 7-12-652 Ran tubing, landed at 6445. Installed tree. Job complete.



U. S. GEOLOGICAL SURVEY

| | | न U. 5. F/ | RMINETON, N. M. |
|---|---------|-----------------------|--|
| 18. I hereby certify that the foregoing is true and correct SIGNED J. H. Watkins | TITLE . | District Office Supv. | DATE 7-21-65 |
| (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: | TITLE _ | | Concession of the second of th |