



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio  
Lease No. 07111  
Unit 1000

## SUNDRY NOTICES AND REPORTS ON WELLS

|  |  |
|--|--|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF        |
| NOTICE OF INTENTION TO CHANGE PLANS            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING       |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT           |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                 |
| NOTICE OF INTENTION TO ABANDON WELL            |  |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 141 is located 42 ft. from N line and 40.3 ft. from E line of sec. 42  
12300 (Range) 211 (Twp.) 12300 (Meridian)  
12300 (Field) 12300 (County or Subdivision) 12300 (State or Territory)

The elevation of the derrick floor above sea level is 1012 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-3-55. Total depth 3300'.  
 Run 2 joints 5 1/2", 10.00, 4-55 casing (3200') set at 3000' with 75 sacks  
 regular cement, 75 sacks - cement, 4-55, 1/2" 11.00, etc.  
 held 1000' for 30 minutes.  
 Top of cement is temperature survey at 2000'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Alamo Natural Gas Company

Address Box 99  
Hamilton, New Mexico

Original Signed W. F. Covert

By \_\_\_\_\_

Title Petroleum Engineer

