



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 07/106  
Unit Lackey

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 1, 1957

Well No. 9-B is located 915 ft. from SW line and 190 ft. from W line of sec. 21

SW Section 21

(1/4 Sec. and Sec. No.)

26N

(Twp.)

9W

(Range)

130M

(Meridian)

Astec P.C. & Blanco

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 6011 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1-17-57, Total Depth 4730'.

Ran 76 joints 5 1/2", 15.50#, J-55 liner, top at 2327' with bottom set at 4729' with 150 sacks regular cement, 150 sacks Pozmix, 4 1/2 Gal, 1, 1/2 Ploccals, sk. Held 1000# for 30 minutes. Top of cement by temperature survey at 2327'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company A. Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

Original Signed EWELL N. WALSH

By \_\_\_\_\_

Title Petroleum Engineer