


STATE OF NEW MEXICO  
**OIL CONSERVATION  
 COMMISSION**  
 DISTRICT NO. 3  
 Phone 99 P. O. Box 697  
 AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)  
**UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 GEOLOGICAL SURVEY**

Land Office Santa Fe  
 Lease No. 067007  
 Unit J. F. Day



**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	<b>X</b>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farmington, New Mexico, November 1, 1951

Well No. C-2 is located 590 ft. from NP line and 990 ft. from EW line of sec. 22

35/4 Section 22 (4 Sec. and Sec. No.)      35/4 (Twp.)      35/4 (Range)      107 W (Meridian)  
Falcone (Field)      San Juan County (County or Subdivision)      New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4105 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Stanolind Oil and Gas Company is taking over operation of above well, effective October 1, 1951

Effective that date well is to be known as Stanolind's J. F. Day No. 2.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanolind Oil and Gas Company

Address Box 147



Farmington, New Mexico

By [Signature]

Title Production Manager

Land Office \_\_\_\_\_  
 Lease No. \_\_\_\_\_  
 Unit \_\_\_\_\_

(SUBMIT IN TRIPLICATE)  
 UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	
SUPPLEMENTARY WELL HISTORY	
SUBSEQUENT REPORT OF ABANDONMENT	
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF WATER SHUT-OFF	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

\_\_\_\_\_ is located \_\_\_\_\_ ft. from \_\_\_\_\_ line and \_\_\_\_\_ ft. from \_\_\_\_\_ line of sec. \_\_\_\_\_

\_\_\_\_\_ (Field) \_\_\_\_\_ (Number of Sections) \_\_\_\_\_ (Meters)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

State name of and expected depths to objective sands and sizes, weights, and lengths of proposed casing, in blocks and in feet, and the details and all other important proposed work.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be conducted.

Company \_\_\_\_\_

Address \_\_\_\_\_

By \_\_\_\_\_

Title \_\_\_\_\_