
GPO 862040

Form 9-881 a (Feb. 1961)



(SUBMIT IN TRIPLICATE)

Land Office Barries Pe	
Lease No.	Mi - CLTTM
Timte	DetA

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS.	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALIER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MARK NA	TURE OF REPORT, NOTICE, OR OTHER DATA)
Well No. 20-D is located 1030 ft. from Well No. 10-D is located 1030 ft. from (4 Sec. and Sec. No.) (Twp.) (Rail Angel Penis Extension	ine and E ft. from E line of sec. E line of sec. E line of sec. E line of sec. E
(Field) (County or Su	bdivision) (State or Territory)
(State names of and expected depths to objective sands; show sizes, wing points, and all other from its depth - 55kl* P.B. T.D 56k0 But logs: top of Pictured Cliffs - 20; Forfersted from 6kg2-kg, 6kg2-6510, to	OF WORK reights, and lengths of proposed casings; indicate mudding jobs, coment- important proposed work) 10, Gallin = 5524, Dakots = 6162
D.V. toni - 2019	aded at 6640' with 250 sacks coment
2nd stage set with 150 sucks coment	
Swebbed hale dry Tested 2 hrs. with 900% pressure Pipe Chay.	K
Swabbed bale dry Tested 2 hrs. with 900s pressure	RECEIVED TO SECOND
Swabbad hale dry Tested 2 hrs. with 900% pressure Pipe Chap.	RELIEF TO SECTION OF THE PROPERTY OF THE PROPE
Swabbad hale dry Tested 2 hrs. with 300° presence Pipe Chap. I understand that this plan of work must receive approval in writing	Ing by the Geological Survey behave paperations than be commenced.
Swebbad hale dry Tested 2 hrs. with 900° ressure Pipe Chay. I understand that this plan of work must receive approval in writi Company Autoc 312 and 3as Company	NOV 22 Little ling by the Geological Sanger before interest heat he commenced.
Rested 2 hrs. with 900 greature Pipe Chay. I understand that this plan of work must receive approval in writi Company Axtee 012 and Gas Company Address Drawer # 570.	ORIGINAL SIGNED BY TOP C. SALMON
Swabbad hale dry Tested 2 hrs. with 900° presence Pipe Chay. I understand that this plan of work must receive approval in writi Company Autor 312 and 3as Company	NOV 22 1000 ling by the Geological Sungey behave interesting they be commenced.