


(SUBMIT IN TRIPLICATE)



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office SAVA  
Lease No. 27-072431  
Unit 10

RECEIVED

MAY 12 1959

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 10 is located 75 ft. from [N] line and 100 ft. from [E] line of sec. 24  
24, Section 24  
(Of Sec. and Sec. No.)  
10, Township 10  
(Twp.)  
10, Range 10  
(Range)  
10, Meridian 10  
(Meridian)  
10, Field 10  
(Field)  
10, County or Subdivision 10  
(County or Subdivision)  
10, State or Territory 10  
(State or Territory)

The elevation of the derrick floor above sea level is 100 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 1971 = 1000 logs = top of the fractured cliffs formation is at 1900. Set 63 joints (1971) of 1/2" casing at 1900 down to 2000. Drilled cement plug 2/1/59. Pressure out to 1900. Cement hole 2000, bottom for two more days 500. pressure = 1000 ft.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 10  
 Address 10  
 By 10  
 Title 10

