



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio
Lease No. 72-000000
Unit Oil

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 100 ft. from N line and 100 ft. from E line of sec. 1
100 (1/4 Sec. and Sec. No.) 100 (Twp.) 100 (Range) 100 (Meridian)
100 (Field) 100 (County or Subdivision) 100 (State or Territory)

The elevation of the derrick floor above sea level is 100 ft. (5, 10)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was drilled 1/20/51
to 100 ft., 100' of 100' casing, lined at 100' with 100' casing on the
bottom casing with 100' casing for 100' casing.
No logs.
Drill: second plug 1/20/51
cased with 100' casing for 100' casing.
No logs to present.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company 100 Oil & Gas Company
Address 100 100
100 100
ORIGINAL SIGNED BY JOE C. SALMON
By Joe C. Salmon
Title 100 100

