

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 27-000781
Unit Oil

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	☒
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 23, 19 59

Well No. 6 is located 1650 ft. from 200 line and 1550 ft. from E line of sec. 15
SE 1/4, Section 15 T-28N R-10W N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artes Pictured Cliffs Santa Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 9914 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth: 2095 Run Logs: Top of the Pictured Cliffs formation at 2022'. Perforated from 2040 to 2080 with four shots per foot.

Set 5 1/2 joints, 2005', at 1/2" casing at 2092' with 75 gal. cement.

Seal the hole 5 1/2 - tested for 2 hours with 500 pressure - API clay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Artes Oil & Gas Company

Address Box 726, Farmington, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON

Title District Superintendent