

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1484.
5. LEASE DESIGNATION AND SERIAL NO.

SF 077111

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Tenneco Oil Company		8. FARM OR LEASE NAME Michener	
3. ADDRESS OF OPERATOR P. O. Box 1714 - Durango, Colorado		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1015' FSL & 1150' FEL		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-28-N, R-9-W	
15. ELEVATIONS (Show whether DF, ST, GR, etc.) 6883' GR		12. COUNTY OR PARISH San Juan	
		18. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDISE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDISING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up, spud 11-2-65, drill to 280'. Ran 8 joints 8-5/8" 24# J-55 casing set at 275'. Cement with 150 sacks. WOC. Drilled out cement and drilled to TD 7635' on 11-24-65. Logged. Ran 238 joints 4-1/2" 10.5# and 11.6# J-55 casing set at 7635'. Stage collars set at 5542 and 3130'. Cement first stage thru shoe with 250 sacks. Stage collar at 5542 would not open, perf collar with 2 holes. Cement second stage thru perfs in collar at 5542' with 130 sacks. Cement third stage thru collar at 3130' with 320 sacks. Good circulation to surface. WOC NOW waiting on completion rig.

RECEIVED

DEC 2 1965

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

RECEIVED

DEC 6 1965

OIL CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Harold C. Nichols

TITLE Senior Production Clerk

DATE November 30, 1965

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Distribution:

- 5 - USGS - Farmington
- 1 - Continental - Durango
- 1 - District File

*See Instructions on Reverse Side