

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)



1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. SF 077111
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado 81302		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1515' FSL, 1765' FEL		8. FARM OR LEASE NAME Storey, "C"
14. PERMIT NO.		9. WELL NO.
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 6375' GR		10. FIELD AND POOL OR WILDCAT Basin Dakota
		11. SEC. T. R. M. OR BLM. AND SURVEY OR AREA Sec. 34, T28N, R9W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☒	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) ☐		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and some pertinent to this work.)*

Rig up completion rig 12-14-65. Cleaned out to 6985', PBTD spotted 200 gal acid on bottom. Perf 6965-6838, 17 holes. Acidized w/1500 gal acid. Frac w/70,000 lbs sand and 93,000 gals water. Perf 6788-6726. Frac w/55,000 lbs sand and 73,000 gal water. Cleaned out and installed tree. Job complete 12-16-65.



18. I hereby certify that the foregoing is true and correct

SIGNED Shirley C. Nichols TITLE Senior Production Clerk DATE 12-20-65

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

5 copies USGS, Farmington
1 copy Continental, Durango
1 copy Tenneco file

*See Instructions on Reverse Side