

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR
J. Gregory Merrion & Robert L. Bayless

3. ADDRESS OF OPERATOR
P.O. Box 507, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1950 FNL & 1850 FWL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>
(other) <input type="checkbox"/>	

5. LEASE
SF-047039B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Bimson

9. WELL NO.
2

10. FIELD OR WILDCAT NAME
Aztec Fruitland

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 17, T28N, R10W

12. COUNTY OR PARISH
San Juan

13. STATE
N.M.

14. API NO.
30-045-22918

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5910' KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Surface reclamation requirements as set forth in the attached letter were completed in September, 1980, and are ready for your final inspection of abandonment.

RECEIVED

SEP 13 1980

U.S. GEOLOGICAL SURVEY
FARMINGTON DISTRICT



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED J. Gregory Merrion TITLE Operator DATE 10-29-80

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:


ACCEPTED FOR RECORD

*See Instructions on Reverse Side

NMOCC

SEP 10 1982

FARMINGTON DISTRICT
BY ETC





United States Department of the Interior

IN REPLY REFER

3100

BUREAU OF LAND MANAGEMENT

Farmington Resource Area

P. O. Box 568

Farmington, New Mexico

87401

June 22, 1978

Mr. Phil McGrath
U. S. Geological Survey
P. O. Box 959
Farmington, NM 87401

Dear Mr. McGrath:

Below are our surface reclamation recommendations for the Merrion and Bayless Bimson #2 in SE $\frac{1}{4}$ NW $\frac{1}{4}$ of Section 17, T. 28N., R. 10W., for which we recently received the subsequent report of abandonment

Both the reserve and mud pits should be filled and smoothed over. The pad should be reseeded using seed mixture #2.

The work should be completed by September 15, 1978.

Sincerely yours,

Robert R. Calkins
Area Manager

WORK COMPLETED SEPT 1980

Enclosure

