

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well

GAS

2. Name of Operator

SOUTHLAND ROYALTY COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1540' FSL, 930' FWL, Sec. 14, T-28-N, R-11-W, NMPM

5. Lease Number

NM-03179

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number

Aztec #7E

9. API Well No.

30-045-24404

10. Field and Pool

Basin Dakota

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - Bradenhead repair

13. Describe Proposed or Completed Operations

- 7-27-95 MIRU. ND WH. NU BOP. TOO H w/2 3/8" tbg. TIH w/gauge ring to 6217'. TOO H. TIH w/5 1/2" RBP & pkr. Set RBP @ 5950', set pkr @ 5919'. Load tbg w/23 bbl 2% KCL wtr. PT RBP & tbg to 1000 psi/15 min, OK. Load csg w/110 bbl 2% Kcl wtr. PT csg to 1000 psi/15 min, OK. Release pkr, TOO H. SDON.
- 7-28-95 RU, ran CBL 0-1000', TOC @ 416'. Perf 3 sqz holes @ 350'. RD. Establish circ out bradenhead w/30 bbl wtr. Pump 145 sx Class "G" cmt w/2% calcium chloride. Circ 5 bbl cmt to surface. POOH. Shut bradenhead valve. Sqz 5 bbl cmt in holes. WOC. SDON.
- 7-29-95 TIH, tag cmt @ 254'. Drill cmt @ 254-350'. Circ hole clean. PT 5 1/2" csg to 1000 psi, failed. TOO H. TIH w/5 1/2" pkr, set @ 413'. Isolate leak @ 350'. TOO H w/pkr. TIE, spot 25 sx Class "G" cmt w/2% calcium chloride @ 155-376'. POOH. Sqz 0.5 kbl cmt into holes. WOC. SD for Sunday.
- 7-31-95 TIH, tag cmt @ 176'. Drill ctm @ 176-376'. Circ hole clean. PT sqz to 1000 psi/15 min, OK. TOO H. TIH w/retrieving head to 5950'. Blow well clean. Latch RBP, TOO H. SDON.
- 8-1-95 TIH, blow well & CO. TOO H. TIH w/197 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 6169'. TOO H. ND BOP. NU WH. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 8/3/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

Date **ACCEPTED FOR RECORD**

CONDITION OF APPROVAL, if any:

AUG 07 1995

FARMINGTON DISTRICT OFFICE
BY [Signature]