


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_

Allottee \_\_\_\_\_

Lease No. **Shawnee Contract No. 274**



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<b>AUG 10 1961</b> <b>U. S. GEOLOGICAL SURVEY</b> <b>SALAMON, NEW MEXICO</b>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**August 9**, 19 **61**

**Boundary Data**

Well No. **1** is located **1000** ft. from **S** line and **1000** ft. from **W** line of sec. **13**

**Sec. 13**  
(1/4 Sec. and Sec. No.)

**Twp.**  
(Twp.)

**2N**  
(Range)

**R. 1E**  
(Meridian)

**Wilcox**  
(Field)

**San Antonio**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **7000** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Shore well has been temporarily abandoned as of August 9, 1961.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Apache Oil and Gas Company**

Address **P. O. Drawer 370**

**Farmington, New Mexico**

ORIGINAL SIGNED BY JOE C. SALMON  
By **Joe C. Salmon**

Title **District Superintendent**