



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. F 078010-A
Unit H

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Nov 2 1963, 19____
Well No. 31-H is located 310 ft. from N line and 330 ft. from E line of sec. 31
20N 13W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Underg (Albaco) San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)
The elevation of the derrick floor above sea level is 5830' ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 5-5/8th hole with rotary mud to 1410' on.
San Logs. PG definitely wet. Desire Plug using
23 sack regular cement spotted from 1150' to 1300'.
Plug top of surface casing with 2 sack sack regular
cement and set pipe marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company McLeod Co o/o Royal Dav Co

Address Box 1299 Albuquerque N M

By [Signature]
A E Shillanter, Agent
Title _____