



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078905
Unit Galleros Canyon Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 26, 1951

Well No. 3 is located 1065 ft. from N line and 890 ft. from W line of sec. 22

SW 22
(1/4 Sec. and Sec. No.)

28N 12 W
(Twp.) (Range)

N.M.P.M.
(Meridian)

Wildcat
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5661 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

9-5/8" casing set at 910' with 155 sacks. Well blew out 8 hours later behind pipe. Pumped 300 sacks mud and 250 sacks cement through Bradenhead. Tested pipe 600' for 30 min. No drop. Tested water shut off 500' for 15 min. No drop.

Understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON & MONTIN

Address 1501 Petroleum Bldg.
Oklahoma City, Okla.

By Ingram Perry
Title Superintendent