

Deviation Checks

State of New Mexico


Lease Gallegos Canyon Unit

County of San Juan

Well No. 141

Location SWNW Sec.22 T28N R12W

<u>Depth</u>	<u>Deviation</u>	<u>Depth</u>	<u>Deviation</u>
236	1/2°		
1250	1°		
2674	1-1/4°		
2850	0°		
3595	1°		
4321	3/4°		
4870	1/2°		
5419	1/2°		



D. E. Hall, of lawful age, being first duly sworn, states that he is District Engineer of the Sunray DX Oil Company; that the above deviation checks are true and correct to the best of his knowledge.

Sunray Dx Oil Company

Witness

By [Signature]
Affiant

Subscribed and sworn to before me this ____ day of _____, 19__.

Notary Public