

Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. I-149-Ind-8475  
Unit I-Sec-844  
**Gallegos Canyon Unit**

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 18 is located 1650 ft. from N line and 900 ft. from E line of sec. 21  
21 (Sec. and Sec. No.) 28N (Twp.) 12W (Range) 10PM (Meridian)  
West 1/4 (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5576 ft. (ground)  
5571 OF

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7/11/52 TD 615' ( 5' under 8 5/8" casing )  
 Bailed hole dry and tested one (1) hour for water shut off.  
 Hole tested dry.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DUNSON AND MONTIN  
 Address Box 3154 West Main St.  
Paradise, New Mexico  
 By Albert R. Greer  
 Title Field Sup't.

# OIL CONSERVATION COMMISSION

## AZTEC DISTRICT OFFICE

No. Copies Received 2

### DISTRIBUTION

	NO. FURNISHED	
Operator		
Santa Fe		
Protraction Office		
State Land Office		
U. S. G. S.		
Transporter		
File		