

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078106
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY Completion report I
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Gallegos Canyon Unit

August 21, 1963

Well No. **136** is located **21.0** ft. from **N** line and **510** ft. from **E** line of sec. **18**

SE/4 NE/4 Sec. 18
(1/4 Sec. and Sec. No.)

T26N
(Twp.)

R12W
(Range)

NMPM
(Meridian)

Totah Gallup
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5822** ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Potential test 8-14-63

45 BO, 0 BM, 143 MCF gas in 24 hrs.

3180 GOR, FFP 70 psi, FCP 380 psi, 36/64" choke.

Final report, well complete.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sunray Oil Company**

Address **200 Petroleum Club Plaza**

Farmington, New Mexico

Original signed by
CHARLES W. ROGERS
By _____

Title **Production Engineer**