

		X
	18	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **078106**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____ X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Gallagher Canyon Unit

December 26, 19**62**

Well No. **130** is located **810** ft. from **N** line and **1850** ft. from **E** line of sec. _____
W 1/4 of **SW 1/4** Sec. **18** **T28N** **R12W** **NMPR**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Totah Gallup **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5629** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 12 1/2" hole at 7:00 p.m. 12-7-62. Drill to TD of 202' and set 202' 8-5/8" 2 1/2" J-55 casing w/125 sx common cement, 21 CaCl. WOC 2 1/2 hours. Drill 7-7/8" hole to TD of 560 1/2'. Run Schl. IPS and Gamma Ray - Sonic logs to 5599'. Run 5-1/2" 17# LTRC N-80 casing to 5580' with Baber "TC" stage collar @ 1713'. Cement 1st stage w/75 sx Incer w/12% Gilsomite and 50 sx Incer cement w/2% CaCl. WOC 6 hours and pressure test to 3000 psi, OK. Cement 2nd stage thru stage collar at 1713' w/125 sx Gilsomite w/12% Gilsomite. Close stage collar and pressure test to 3000 psi, OK. Job complete @ 6:30 a.m. 12-20-62. Preparing to complete.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sunray Oil Company**
Address **200 Pet. Club Plaza Bldg.**
Farmington, New Mexico

By **CHARLES W. ROGERS**
Title **Production Engineer**

