L & B Speed Drill, Inc.

James L. Ludwick

P.O. BOX 70 • FARMINGTON, NEW MEXICO 87499-0070 • (505) \$25-1079

August 12, 1995

R & G DRILLING CO. P.O. BOX 2669 FARMINGTON, NM 87499

RE: DEVIATION REPORT ON THE KRAUSE WELL #94, NE¹/₄, Sec. 28 T28N. R11W, SAN JUAN COUNTY, NM.

Below is the deviation report on your Krause Well #94.

120' 1/2°

850' 3/4°

1750' 3/4°

SIGNED & ACKNOWLEDGE BY:

JAMES L. LUDWICK, PRESIDENT

DATE: 8/12/95



KM PRODUCTION COMPANY P. O. Box 2406 Farmington, NM 87499-2406 (505) 325-6900

DECEIVED AUG 2 4 1995

OIL CON. DIV. DIST. 3

SLOPE TEST

Depth	Hole Deviation
120 feet	1/2 degree
850 feet	3/4 degree
1750 feet	3/4 dearee

State of New Mexico)) ss	
County of San Juan)	
I, Kevin H. McCord , being first duly sworn,	
depose and state that the above and foregoing depth and hole	
deviation figures are true and correct to the best of my	
information and belief. MM M	
(7	
Subscribed and sworn before me this 23rd day of August, 19 95.	
Notary Public	

My Commission Expires