

District I

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources DepartmentOIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND REPORT TO

SANTA FE OFFICE

Denny S. [Signature]
DEPUTY OIL & GAS INSPECTOR

SEP 5 1995

PIT REMEDIATION AND CLOSURE REPORTOperator: Phillips Petroleum Company Telephone: (505) 599-3400Address: 5525 Hwy. 64, NBU 3004, Farmington, NM 87401Facility Or: San Juan 29-6 Unit #9
Well NameLocation: Unit or Qtr/Qtr Sec SW SW Sec 36 T 29N R 6W County Rio ArribaPit Type: Separator ☒ Dehydrator ☐ Other Condensate TankLand Type: BLM ☐ State ☒ Fee ☐ Other ☐Pit Location: Pit dimensions: Length 25', width 25', depth 4'
(Attach diagram) Reference: wellhead ☒ other ☐
Footage from reference: 25
Direction from reference: 0 Degrees ☒ East North ☐
West South ☐Depth to Ground Water: 80'
(vertical distance from
contaminants to seasonal
highwater elevation of
ground water)
☒ Less than 50 feet (20 points)
☐ 50 ft to 99 feet (10 points)
☐ Greater than 100 feet (0 points) 10Wellhead Protection Area:
(less than 200 feet from a private
domestic water source, or: less than
1000 feet from all other water sources).
☐ Yes (20 points)
☒ No (0 points) 0Distance to Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)
☐ Less than 200 feet (20 points)
☐ 200 feet to 1000 feet (10 points)
☒ Greater than 1000 feet (0 points) 0

PITCFRM.WK3

RANKING SCORE (TOTAL POINTS): 10

Date Remediation Started: n/a Dated Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____
(Check all appropriate sections)

General Description of Remedial Action: n/a

Initial assessment showed soils to be clean at the surface and at
three feet below pit bottom.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 3' below pit bottom

Sample date 9-3-93 Sample time _____

Sample Results

Benzene (ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) 0

TPH 0

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 8/18/94 PRINTED NAME Ed Hasely

SIGNATURE Ed Hasely and TITLE Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT SUMMARY
REVISED DATE SEPTEMBER 09, 1993

REO

1993

ENVIROTECH, INC.

REVISED DATE: SEPTEMBER 09, 1993													REO		EPA METHOD 8020 (PPB)									
PIT NO	WELL NAME	PIT TYPE	RANK SCORE	CLOSURE STANDARD (PPM)	DATE 1993	GROUNDWATER SAMPLE RECOVERED Sub-Surf. Data	SOIL TYPE	PIT TYPE	SAMPLE NO.	Organic Vapor Mass (PPM)	Total Recoverable Pet. Hydro. (PPM)	METHOD 5030 PURGE-AND-TRAP					TOTAL BTEX	STATUS						
												Benzene	Toluene	Ethyl Benzene	Xylene									
PA056	SAN JUAN 29-6, #25	M362906	SEP	10	1000	9-03	NO	CL	EARTHEN	T1-4.5 T1-7	0 0	0							CLOSE					
PA057	SAN JUAN 29-6, #25	B322906	SEP	10	1000	9-03	NO	SM	EARTHEN	T1-4 T1-6.5	718 851	100	15.3	97	23.3	272	407.6		CLOSE					
PA058	SAN JUAN 29-6, #55A	C182906	SEP	20	100	9-03	NO	SM	EARTHEN	T1-6 T1-11 T1-14 T2-5 T2-10 T2-15	685 555 512 6 43 629	1800 2000 3300 10 1600						REM						
PA059	SAN JUAN 30-5, #95 DK	H283005	SEP	10	1000	9-07	NO	CL	EARTHEN	T1-4.5 T1-7	195 87	0							REM ?					
PA060	SAN JUAN 31-6, #37 DK	P363106	SEP	0	5000	9-07	NO	SM	EARTHEN	T1-4	50	4400							CLOSE					
PA061	SAN JUAN 31-6, #42 DK	A363106	SEP	0	5000	9-07	NO	SP	EARTHEN	T1-2.5	17.1	760							CLOSE					
PA062	SAN JUAN 31-6, #38 DK	C023006	SEP	0	5000	9-07	NO	CL	EARTHEN	T1-5.5 T1-8	1.6 24	34							CLOSE					
PA063	SAN JUAN 31-6, #48 DK	P023006	SEP	0	5000	9-07	NO	CL	EARTHEN	T1-4 T1-6.5	23 23	0							CLOSE					
PA064	SAN JUAN 31-6, #46	A323106	SEP	20	100	9-08	NO	CL	EARTHEN	T1-6.5 T1-9	10 0	0							CLOSE					
PA065	SAN JUAN 31-6, #47 DK	L323106	SEP	0	5000	9-08	NO	CL	EARTHEN	T1-5 T1-7.5	20 53	12							CLOSE					
PA066	SAN JUAN 29-6, #15-2	K022906	SEP	10	1000	9-08	NO	CL	EARTHEN	T1-4.5 T1-7	5 905	110	42.9	590	328	7570	8520.9		CLOSE					
PA067	SAN JUAN 29-6, #37-16	A162906	SEP	10	1000	9-08	NO	CL	EARTHEN	T1-4.5 T1-7	707 817	44	16.4	710	24.6	498	1249		REM ?					

ENVIROTECH Inc.

5796 US HWY 64. FARMINGTON. NM 87401
(505) 632-0615

FILE NO: PA056

C.O.C. NO: _____

FIELD REPORT: SITE ASSESSMENT

JOB No: 93163
PAGE No: 1 of 1

PROJECT: PIT ASSESSMENT
CLIENT: PHILLIPS
CONTRACTOR: ENVIROTECH, INC.
EQUIPMENT USED: CASE EX TO DAD16

DATE STARTED: 9-3-93
DATE FINISHED: 9-3-93
E/MIRO. SPCLT: RED
OPERATOR: CLIMARKIN
ASSISTANT: HS

LOCATION: LEASE: SAN JUAN 29-6 WELL: #9 QD: 990' FSL, 990' FWL (M)
SEC: 36 TWP: 29N RNG: 6W PM: NM CNTY: R.A. ST: NM PIT: SEA

LAND USE: RANGE - LEASE # E 2893

SURFACE CONDITIONS: EARTHEN PIT - NO STAINING

FIELD NOTES & REMARKS: PIT IS LOCATED APPROXIMATELY 25 FEET EAST OF WELLHEAD.

CLOSURE STD: 1000 PPM TPH

T1: Brown, moist, organic silty clay, med. plastic.

RANKING SCOPE: 10

NO ODOR OR STAIN.

[illegible]

GAC 0201


SCALE

PIT IS APPROX 25' x 25'

--	--	--

0 10 20 FEET

SITE DIAGRAM



TEST HOLE LOGS

	TH#:	SOIL TYPE	SAMPL TYPE	OVM/ TOL
GS				
1				
2				
3				
4	PIT Bottom			
5	OL GFS ND			
6				
7	- OL GFS ND			
8	TB = 7'			
9				
10				

[illegible]