


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. 079033

Unit San Juan 29-5 Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	JUN 16 1958	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	U. S. GEOLOGICAL SURVEY	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	FARMINGTON, NEW MEXICO	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 11, 1958

Well No. 39-23 is located 990 ft. from S line and 700 ft. from W line of sec. 23

SW Sec. 23
(1/4 Sec. and Sec. No.)

29N
(Twp.)

5W
(Range)

N.M.P.M.
(Meridian)

Blanco
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6201 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6-5-58, Total Depth 4008'.

Ran 123 joints 7 5/8", J-55, 26.40#, casing (3996') set at 4007' with 75 sacks regular cement, 75 sacks Pozmix, 30# Floccule and 2# gel, followed with 50 sacks Best cement, with 2# CaCl.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 3000'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Original Signed D. C. Johnston

Title Petroleum Engineer