

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. 07942Unit San Juan 23-614-28-001-433UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS


NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 26, 19 60Well No. 65-19 is located 900 ft. from N line and 440 ft. from E line of sec. 19N.E. 1/4 Sec. 19
(1/4 Sec. and Sec. No.)29 N
(Twp.)6 W
(Range)N.M.P.M.
(Meridian)Blanco M.V.
(Field)Rio Arriba
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 9453 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6-19-60, Total Depth 3557.Ran 57 gal. 7 5/8", J-35, 26.40 lb, casing (3545) set at 3555'with 120 lbs. reg. cement, 2 lb Calcium Chloride 2, 1/2 cu.ft. Strata-Crete 100.Held 1000 lb 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas CompanyAddress Box 900Farmington, New MexicoBy ORIGINAL SIGNED J.J. TILLERSONTitle Petroleum Engineer

