

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE
GAS INSPECTOR

DEPUTY OIL & GAS INSPECTOR

JEP 15 1995

PIT REMEDIATION AND CLOSURE REPORT

Operator: PHILLIPS PETROLEUM COMPANY **Telephone:** (505) 599-3460

Address: 5525 Hwy. 64, NBU 3004, Farmington, NM 87401

Facility Or: San Juan 29-6 Unit #26 (MV)

Well Name

Location: Unit or Qtr/Qtr Sec NE SW Sec 13 T 29N R 6W County Rio Arriba

Pit Type: Separator^X Dehydrator Other Condensate Tank

Land Type: BLM ☒, State ☐, Fee ☐, Other ☐

Pit Location: Pit dimensions: length 30', width 30', depth 4
(Attach diagram)

Reference: wellhead X , other

Footage from reference: 70'

[illegible]

Depth To Ground Water: 140
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Wellhead Protection Area:

(Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)

Distance To Surface Water:

(Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)

Less than 50 feet	(20 points)	
50 feet to 99 feet	(10 points)	
Greater than 100 feet	(0 Points)	0

RECEIVED
MAY - 9 1994
OIL CON. DIV.
DIST. 3

Yes (20 points)
X No (0 points) 0

Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
x Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: N/A Dated Completed: _____

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: N/A

Initial assessment of pit showed soils to be clean
at the surface and at three feet below pit bottom.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location Deepest part of pit. Sampled with a backhoe.
Closure Sampling: _____
(if multiple samples, attach sample results and diagram of sample locations and depths)
Sample depth 3 ft below pit bottom
Sample date 1-18-93 Sample time -

Sample Results

Benzene(ppm) -
Total BTEX(ppm) -
Field headspace(ppm) 2.5
TPH 10

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE

4-13-94

SIGNATURE

Ed Hasely

PRINTED NAME
AND TITLE

Ed Hasely
Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT SUMMARY
REVISED DATE: NOVEMBER 22, 1993

HEO

1993

ENVIROTECH, INC.

PIT NO.	WELL NAME	U-S-T-R	PIT TYPE	RANK SCORE	CLOSURE STANDARD TPH (PPM)	DATE 1993	CONTAMINANTS Sub-Surf Depth	SOIL TYPE	PIT TYPE	SAMPLE NO.	Organic Vapor Meter (PPM)	Total Recoverable Pet. Hydro. (PPM)		EPA METHOD 8200 (PPB) AND-TRAP					TOTAL BTX	STATUS
												Benzene	Toluene	Ethyl Benzene	Xylene					
PA087	SAN JUAN 29-0, #73A	D202906	SEP	10	1000	11-11	NO	CL/SP	EARTHEN	T1-4 T1-6.5	3.8 5	12								CLOSE
PA088	SAN JUAN 29-0, #74A	I202906	SEP	10	1000	11-11	NO	CL/SP/SM	EARTHEN	T1-7 T1-12 T1-15 T2-13	606 826 1124 0	7200 4800 2500 10								REM
PA089	SAN JUAN 29-0, #41-24	A242906	SEP	0	5000	11-17	NO	CL	EARTHEN	T1-4.5 T1-7	41 2047	110	2510	28200	2200	50000	82910			REM
PA090	SAN JUAN 29-0, #80	H242906	SEP	0	5000	11-17	NO	CL/SP	EARTHEN	T1-4 T1-6.5	46 131	1200	0	0	0	262	262			CLOSE
PA091	SAN JUAN 29-0, #82	A252906	SEP	10	1000	11-17	NO	SC	EARTHEN	T1-5	36	940								CLOSE
PA092	SAN JUAN 29-0, #42-25	H252906	SEP	10	1000	11-17	NO	CL	EARTHEN	T1-6.5	721	580	4390	19700	102	7000	31191			CLOSE
PA093	SAN JUAN 29-0, #70	M242906	SEP	0	5000	11-17	NO	SM	EARTHEN	T1-4.5 T1-7	587 103	1200	0	418	22	550	990			TEST
PA094	SAN JUAN 29-0, #40-23	H232906	SEP	0	5000	11-17	NO	CL	EARTHEN	T1-4.5 T1-7	3.2 909	20	136	830	51	1133	2253			CLOSE
PA095	SAN JUAN 29-0, #75	H232906	SEP	0	5000	11-17	NO	CL	EARTHEN	T1-4.5 T1-7	0 0	0								CLOSE
PA096	SAN JUAN 29-0, #27	K232906	SEP	0	5000	11-18	NO	CL	EARTHEN	T1-4.5 T1-7	0 0	0								CLOSE
PA097	SAN JUAN 29-0, #83	M132906	SEP	0	5000	11-18	NO	CL	EARTHEN	T1-2 T2-2 T3-2	26 0 0	4800 86 20								CLOSE
PA098	SAN JUAN 29-0, #20-13	K132906	SEP	0	5000	11-18	NO	SC	EARTHEN	T1-4.5 T1-7	0 2.5	10								CLOSE
PA099	SAN JUAN 29-0, #103	G112906	SEP	10	1000	11-18	NO	SC/SM	EARTHEN	T1-1.5 T2-2	134 2.5	15100	310	0	700	11500	12510			REM
PA100	SAN JUAN 29-0, #84	G142906	SEP	10	1000	11-18	NO	CL	EARTHEN	T1-4.5 T1-7	58 758	680	106	2000	167	3030	5393			CLOSE
PA101	SAN JUAN 29-0, #104	N142906	SEP	10	1000	11-19	NO	CL	EARTHEN	T1-3.5 T1-6	0 0	0								CLOSE
PA102	SAN JUAN 29-0, #93	B162906	SEP	10	1000	11-19	NO	SM	EARTHEN	T1-5	20	690								CLOSE

