#### (SUBMIT IN TRIPLICATE)

#### Santa Fe Land Office Lease No.

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Unit Sen	Ausn	29-5	Unit

# SUNDRY NOTICES AND REPORTS ON WELLS

Bection 7 (1/4 Sec. and Sec. No.)	(Twp.) Sen Juan	$ \begin{array}{ccc} \text{M.1} & \text{S} & \text{line and} & \text{M.2} \\ \text{S} & \text{M.3} & \text{M.4} \\ \text{(Range)} & \text{(Merconstruction)} \end{array} $	ft. from E line	
Il No. 50 is loc  Section 7 (4 Sec. and Sec. No.)	(Twp.)	1750   S   line and   1750   S	idian)	
Il No. 50 is loc  Section 7 (4 Sec. and Sec. No.)	ated ft. from	n. S line and 1750	ft. from $\begin{cases} \mathbf{E} \\ \mathbf{M} \end{cases}$ line	of sec. 7
ll No. 50 is loc	ated 1750 ft. from	$S$ line and $\frac{173}{1}$	ft. from E line	of sec. 7
11 NT 50	. 1750			
	•	Markey		, 19 <u>-</u>
		April 17,		106
		K NATURE OF REPORT, NOTICE,		
OTICE OF INTENTION TO ABANDO	DN WELL			
NOTICE OF INTENTION TO SHOOT OR ACIDIZE				
		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING  SUBSEQUENT REPORT OF ALTERING CASING.  SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.  SUBSEQUENT REPORT OF ANADOMMENT		
		SUBSEQUENT REPORT OF WATER SHUT-OFF		

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 4-15-61 Total Depth 270'.

Ran 6 joints of 20" conductor pipe set at 250'. Ran 8 joints 4 1/2" drill pipe, Commuted 20" casing with 425 macks regular 25 calcium chloride. Circulated to surface. Held 600#/30 minutes.



I understan	d that this plan of work must receive approval in writir	ng by the Geological Survey before operations may be commenced.
Company .	H1 Paso Natural Cas Company	a commenced.
	Box 990	
	Farmington, New Hexico	ByOdgle-1 Signed D. W. Meehan
·		Title Petrolem Engineer